

# It's just a bit of hot weather ...



In fact, hot weather can cause the overhead lines to expand and sag. To avoid damaging the lines, trains must travel more slowly than normal.



Check your train  
is running on time

---

[nationalrail.co.uk/summer](https://nationalrail.co.uk/summer)